

500i Recovery Procedure (Feb 14, 2021)

1. Transfer the [flash.bin](#) file to the root directory of a USB drive (FAT32 formatted).
2. Ensure that the receiver is powered off, then plug the USB drive into the receiver.
3. While turning on the receiver, press the **MUTE** button repeatedly until you see a message on the screen that says “**USB Upgrade! Do not power off!**”
4. When the upgrade is complete (should take about 2-3 minutes), the receiver will restart itself automatically.